	EDITIONS	CLASSIFIED MESSAGE	governmenters survey survey and enterest to the survey of	NFG. 603
!	Approved For Release 2003		00 016 0010134-	ROUTING
	DATE . 1945 Z 30 JUL 64	SECRET	2	TO THE PARTY OF THE PROPERTY OF THE PARTY OF
	The agent		S .	
	* NYT TOMPHONE SIZE IN	Not the contrasporting the secretary contrasport of the second of the se	14	12
	TO DIRECTOR	magaman i, da ar shifte - populari vi shipe shimas vi sha ciped-adac, si c (shaftan dhip to populari (ship) a Labella i c milli dishibita a labella	6	13
5 1/4			7	manuse se su su demonstrato se se su
5X1	FROM :			16
!	ACTION:			ROUTINE
	INFO :		The standard of the standard o	
i	OPS 1-8 &		p#	IN 90361
!	TOR 2052Z 30 JUL 64			25X1
5X1	TO PRIORITY MFO	er e	CITE	75X1
5X1 ,				
•	SUBJECT: FILM EVALUATION	MISSION SI84A		

2. ORIGINAL NEGATIVE:

PROCESSING WAS ACCOMPLISHED BY

2

A. THE EXPOSURE WAS ADEQUATE BUT THE RESOLUTION IS ONLY FAIR AT BEST. DEGRADATION IS ATTRIBUTED TO ATMOSPHERIC HAZE AND LOW TERRAIN REFLECTIVITY.

CAMERA B 12 WAS USED IN MISSION S184A FLOWN 12 APRIL 1964.

25X1

9R SIDE: TWO ROWS OF DESENSITIZED (MINUS-DENSITY) 9. SPOTS ARE PRESENT FROM HEAD TO TAIL ALTHOUGH NOT ALWAYS READILY DETECTABLE. ONE ROW IS PARALLEL TO AND 1.25" FROM THE OUTBOARD (TITLED) EDGE OF THE FILM AND THE OTHER IS PARALLEL TO AND 0.20° FROM THE INBOARD EDGE. THE SPOT-TO-SPOT SPACING IN BOTH ROWS IS 1.55". FRAME 133 CONTAINS FOREIGN MATTER (THREADS AND INK STAINS) AND A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 178 FRAMES 265 AND 266 WITH ASSOCIATED CREASES IN FRAMES 178-181. WERE TORN AND TAPE-REPAIRED AT THE PROCESSING SITE. PART 7 (FRAMES 799-931) CONTAINS PINHOLES DEGRADE FRAME-804 GROUP I SECRET

Approved For Release 2003/11/25 : CIA-RDP74B00836R000100010134-1
REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy N

(IN 90361) SECRET PAGE TWO
A FINE PLUS-DENSITY STREAK PARALLEL TO AND 4" FROM THE INBOARD
EDGE OF THE FILM. THIS STREAK IS CONTINUOUS AT FIRST BUT
EECOMES INTERMITTENT BEFORE RUNNING OUT.

- C. 9L SIDE: TWO ROWS OF DESENSITIZED SPOTS SIMILAR TO
 THOSE NOTED IN THE 9R SIDE ARE PRESENT THROUGHOUT THE FILM.
 THE INBOARD ROW PARALLELS THE EDGE AT A DISTANCE OF 0.40° AND
 THIS IS THE ONLY DEVIATION FROM THE MEASUREMENTS LAID OFF IN
 ITEM 2(B) ABOVE. CAMERA ROLLER-INDUCED STATIC DISCHARGES (ROLLER
 CHATTER) ARE PRESENT ALONG THE INBAORD EDGE BUT DISSIPATE APPROXIMATELY MIDWAY THROUGH THE MATERIAL. FRAMES 038-041, 257263 AND 2222-2230 CONTAIN A CONTINUOUS MINUS-DENSITY STREAK
 ROUGHLY PARALLEL TO AND 0.75° FROM THE OUTBOARD EDGE OF THE
 FORMATS. A FINE CONTINUOUS MINUS-DINSITY STREAK RUNS PARALLEL
 TO AND 0.05° FROM THE INBOARD EDGE THROUGHOUT MOST OF THE FILM.
 IT IS NOT DETECTABLE IN THE LAST 25 PERCENT OF THE TAKE.
- D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 016-2486 AND 2524-2700. FRAMES 001-016 AND 2487-2523 WERE EDITED OUT PRIOR TO EVALUATION.
- E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.
 - 3. DUPLICATE POSITIVE:
- A. THE PI SUITABILITY RANGES FROM POOR TO FAIR. HAZE
 DEGRADATION AND LOW CONTRAST PHOTOGRAPHY COMBINE TO MAKE TARGET
 IDENTIFICATION AND ANALYSIS DIFFICULT.
 - B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUD COVER OBSCURES APPROXIMATELY 30 PERCENT OF THE REMAINDER TO Approved For Release 2003/11/25: CIA-RDP74B00836R000100010134-1